

REMINGTON ARMS COMPANY, INC. - ILION WORKS  
Investigator's Copy of Suggestion

NAME: CHURCH PROSSER 82 20692  
JERRY BURNS 82-24443

SUGGESTION NO: 75C-13816

CLOCK NO: \_\_\_\_\_

DATE RECEIVED: 1-19-73

M/580-1-2; 591-2; 788 Trigger Housing Assembly. Change design of Safety and Sear. Alter the M/540I Sear to provide a notch to control engagement between the Sear and Trigger which will not affect its use on the M/540I. Alter the M/580 & 788 Safety to function like the M/540I with the Sear instead of actuating a Safety Plunger. Make minor change to M/580 & 788 Housing to provide clearance for the M/540I type Sear and substitution of the M/540I Safety Plunger and Spring for the M/580 & 788 Safety Plunger and Spring. (NOTE: R&D has marked prints). Eliminate Trigger Housing Sub Assy Op. #10-12-15R. Eliminate scrap that is now produced at Op. #10. Improve quality by reducing play between Sear and Trigger.

SUPERVISION -

This Suggestor is a member of your area. PLEASE GIVE THIS YOUR PROMPT ATTENTION AND COMMENTS.

If the Suggestion should not be adopted, please write your detailed reasons, as the Suggestor deserves every consideration possible.

If it is adaptable, you are expected to expedite its installation or contact the respective Section (Engineering, Production, Safety, PE&C, etc.) for approval or assistance.

When it is in effect, return all answers to the Suggestion Committee Secretary.

E. R. Carr - 2/6/73

*your comments please!*

*Design has made up models &  
they are being evaluated  
Hann 2/8/73*

RD-6562

R. H. Brown  
 Secretary, Suggestion Committee