

MODEL SHOP WORK LOAD AS OF 10-21-74WORK ON HAND3200

BARREL ASSY. (CUT OFF)

10-25

10-2

FRAME-TOP TANG ALT.

10-23

10-2

BARREL SPACER

10-21

10-2

1100

RECEIVER (ALT.)

10-30

10-3

FEEDLATCH RETAINER

10-30

10-3

FEED LATCH (ALT.)

10-30

10-3

XP CASE

FIRING PIN SEAL

10-25

10-2

1100 X

LINK

10-28

10-2

ACT BAR SLEEVE

10-28

10-2