

February 10, 1975

Remington Arms Inc.
% Jack Chisnell
939 Barnum Ave.

Dear Sir:

Subsequent to our conversation on Tuesday, Feb. 4, 1975, I have gone to Temple and picked up the 243 Mohawk. I also have pictures of the damage to the seat cover and an estimate to have the damage repaired. These are enclosed.

Two gunsmiths have checked the gun and they have confirmed that there is a default in the gun causing it to discharge as I explained in our conversation of last week. For the gun to discharge, the safety has to be put between safety and fire. Pull on the trigger and a small click can be heard. Pulling it all the way back to safety, the gun will then go off when it is put on fire. The gun is now on safety with no shells in the gun. After unpacking the gun, without pulling the trigger, the gun will fire if you push it to fire.

Subsequent to our conversation, I have discussed this with my nephew and he would rather have the 25/06.

Enclosed are the pictures, estimate, and a copy of the BankAmericard charge.

I'm very grateful for the co-operation shown me by you after I could get no co-operation from Carter's in Houston.

If anything else is needed, please contact me.

John W. Ralston
John W. Ralston
3026 Larknolls
Houston, Texas 77028
Area Code 713 686-3400

RECEIVED

FEB 18 1975

PRODUCT SERVICE