

PRESENT

5.027 / 8

Pr: 2000

247-155

500

additional time to check safe at 'U' setting
from position 4010 final inspection

1. Push safe on "U" .010
2. Remove bolt (should come out) .039
3. Reassemble bolt .039
4. Try to fire (should not) .011

1.097 MIN. = 1.65 HRS/c

Add. 1.81 HRS/c

Final Assy 220

Final Insp .691

STAMP RECEIVER OPER. 167

APL 012 MIN. or 030 HRS $\times 3.02 = 0757/c$

JP