

GUNSMITH CALL REPORTDate April 24, 1975Reporter E. WoodrickShop Name Tillman Gun Shop, Inc.Gunsmith's Name Mr. Ken BearmanAddress 1025 Maumee Ave., Fort Wayne, Ind. Zip 46803
No. & Street City StateGunsmith on Premises? X If not, give address below:Gunsmith's Address _____ Zip _____
No. & Street City State

Recommended List (X) Open Acct. (X) 30% Disc. _____ Dealer (X) Large () Small (X)

PERSONS INTERVIEWED and POSITION:

- (1) Mr. Leonard S. Sieminski, Mgr. (2) Mr. Ken Bearman, Gunsmith
 (3) _____ (4) _____

SPECIFIC PROBLEMS ENCOUNTERED:

- 1 M76 22 -- Would not fire at times when safety was released.
 1 M66 22 -- Cartridges would jam (Cart. Stop Spring missing)
 1 M700 BDL 25/06 6611418 Fired when safety was released—
 (Trigger pull had been adjusted to 1#)
 1 M742 30/06 7492056 FE Bolt would not unlock.

GENERAL DISCUSSION

Since my last visit to this shop both of the above men are new and was able to cover the above guns and assist in the repairs. The M76 had been in the shop for some time and was about to send it to the plant along with the new M742 in which the bolt could not be opened. This M742 had the tip of the bolt latch broken which was binding the bolt not allowing it to move, after getting the gun apart and replacing this latch the gun would operate. The M700 gun had been adjusted so the pull was only a pound and would follow down when the safety was released—after properly adjusting to 3½# the gun functioned properly and could not be tricked for any failure. In discussing the M1100 nothing specific was brought out as causing trouble, was told the biggest trouble seems to be the customers use them and put the gun away without any cleaning allowing them to rust causing the gun to fail. Both men commented that Remington