

63 Rev.

GUNSMITH CALL REPORT

CO: B B Spencer

Reporter p Name Gunsmith's Name ress Zip No. & Street City State smith on Premises?

If not, give address below:

smith's Address No. & Street City State Zip omended List () Open Acct. () 50% Disc. Dealer () Large () Small ()

PERSONS INTERVIEWED and POSITION:

1 Mr. Chuck Martens Owner (2)) (4) SPECIFIC PROBLEMS ENCOUNTERED:

- 1 M 700 25/06 Code LW Shows rust around the front sight.
- 1 E 700 25/06 Code LW Stock damaged by the bolt handle--~~a safety inoperative--~~
(Safety bail missing--which I replaced)
- 1 M870 8197409 V Code JT poor patch in stock & color--on barrel shows much discoloration & rust.
- 1 M870 8326363 Code XF coloring coming off barrel & being spotted.
- 1 M870 8658532 Code RW Poor polish in bore, (shows several rough spots half way in the bore)
- 1 M870 8509795 V Code LW Barrel appears to be dry & sticky--in wiping it down much discoloration comes off and coloring is spotted.

(all above barrels will be returned for correction)

GENERAL PROBLEMS

Radio shop reported that a considerable number of feed latches are still showing up along with complaints on burr wood & coloring. Had a M74 that could not be taken down as it need a new port cover & operating handle,--and had a good wrench to remove the barrel take down nut. I was shown several guns with defective bluing & poor patch in the wood along with finish. I advised that if it was something I would not accept as satisfactory for myself to return it to the factory for replacement. Showed the M300 a little bit with some black around the gun holding it