## BARBER - PRESALE R 0105433

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

xc: J. P. Linde Lab File

Remington.

PETER!

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"\_

Ilion, New York December 15, 1975

TO:

W. E. LEEK

FROM:

A. A. HUGICK

DATE:

DECEMBER 10, 1975

SUBJECT:

M/700 SAFETY EVALUATION - REPORT #8

Work Order:

E 0262

#### INTRODUCTION:

Design initiated a review of the bolt action rifle safety function. The final phase of this program involved the M/700 rifle. Consideration of standardizing on safety detent system between the 700 & 600 rifle control systems. Three M/700 rifles were delivered for safety dry cycle evaluation in the measurement and test dry cycle equipment. This allows M/700 trigger housings to be used in the M/600.

### TEST OBJECTIVE:

Dry cycle test the sample M/700 rifles with safety detent system compatible with M/600 fire control system.

#### TEST RESULTS & OBSERVATIONS:

1. M/700 - S.N. 6898412 - Test Gun #1

Test Activity

- 50,000 Safe On Safe Off cycles.
- 10,000 Cock and Dry fire Cycles.
- W. D. 40 lubrication.
- Design fabricated rifles.

Test Results

- Sear lift data showed variations Min. .007
  - to max. -.009.
- Sear lift data indicated no trend.
- Safe on force variation ranged from 7.5 lbs. max.
  - to  $4.5 \, \text{min}$ .
- Safe Off force variation ranged from 5.5 lb. max.
  - to 3.0 min.
- Striker & fire control parts inspection indications were good (A.)

To: W. E. Leek From: A. A. Hugick

M/700 Safety Evaluation - Report #8

December 15, 1975

Page 2

TEST RESULTS & OBSERVATIONS: - Contd.

2. M/700 - S. N. 6898446 - Test Gun #2

- Test Activity 50,000 Safe On Safe Off cycles
  - 10,000 cock & dry fire cycles
  - WD 40 lubrication
  - Design fabricated rifles.

Test Results

- Sear Lift data showed variations min .0048 to max .0073.
- Graphing of data indicated a sear lift decrease trend.
- Safe On force variation ranged from 6.0 lbs max. to 3.25 min.
- Safe off force variation ranged from 6.5 lb max. to 3.50 min.
- Striker and fire control parts inspection indications were good.
- 3. M/700 - S. N. 6897681 - Test Gun #3

Test Activity

- 50,000 Safe On Safe Off cycles
- 10,000 cock & dry fire cycles
- W D 40 lubrication
- Design fabricated rifles

Test Results

- Sear lift data showed variations between min .0053 and max .0068 inches.
- Sear lift data indicate a minor trend of decreasing.
- Safe on force variation ranged from 6.0 lbs. max. to 3.50 min.
- Safe off force variation ranged from 6.0 lbs max. to 3.75 min.
- Striker and fire control parts inspection indications were good.

AAH:bd Measurement/Test Lab Ilion Research Division To: W. E. Leek From: A. A. Hugick

M/700 Safety Evaluation - Report #8

December 15, 1975

# BOLT ACTION RIFLE SAFETY EVALUATION PROGRAM 3 × M/700 RIFLES FOR DRY CYCLE EVALUATION

- A. Trigger pull, Safe On force, Safe Off force Safe On - Lift of sear at trigger.
- B. Check function of safe.
- C. Clean and lubricate fire control (WD 40)
- D. 10,000 Safe on Safe Off dry cycles.
- E. Repeat "A"
- F. Repeat "B", and "C"
- G. Repeat "D"
- H. Continue test to a total of 50,000 Safe On - Safe Off dry cycles.
  - I. Repeat "A", "B", and "C"
  - J. 10,000 cock and dry fire cycles.
  - K. Repeat "A" and "B"
  - L. End of Dry cycle test

9/17/75 A. A. HUGICK

AAH:bd