

Dec. 30, 1975

DRAFT

FIELD SERVICE MANUAL

Model 700 - 600 (Cont'd.)

A broken connector can cause a follow down condition.

Check what 1/8 turn given on 700 & 600 fire control adjustment.

On all rifles the safety operation should be checked after the rifle is re-assembled for any reason. The rifle should be put in the on safe condition.

The trigger pulled, the trigger released and safety switched to the fire position, the trigger should then be pulled to verify, gun will fire, repeat test 3 times.