Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

Owners of the above guns should contact one of the following gunsmiths:

In Anchorage Howard's Gun Shop 528 Fifth Avenue Anchorage, Alaska 99501 Anchorage, Alaska 99507 (907) 272-4570

In Anchorage Bill's Gun Shop 8729 Lake Otis Parkway (907) 349-1312

In Fairbanks Dixon's 261 College Road Fairbanks, Alaska 99701 (907) 456-8742

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.