

Faded by mail 10 Gun Repair Stations

11-8-78 to 11-15-78

a trip was made to visit 12 Remington warranty repair stations concerning the model 600 recall program.

Reception at all gun repair stations was very good. They were all glad to see someone from Remington to go over the recall program, all stations had received at least 5 trigger assemblies with about half of them having received a second 5. The first five assemblies were individually wrapped. The second five were wrapped together in one package. One assembly had a slange pin missing but was still intact.

Some of the stations did not ^{completely} understand that serial numbers with the A & B prefix were not included in the recall program and a few had changed trigger assemblies in rifles with an A prefix.

Most of the stations that had X.P. 100 pistols had been instructed by their customers not to return them to the factory.

Individual stations contacted along with comments are listed below.

TO: C B Workman
FROM: J W. Brooks