

1978 XP100 RECALL INFORMATION

In 1978, XP-100's with a serial number below 7507984, except those with a prefix "A" or "B" before the numbers, were recalled for trigger assembly replacement.

XP-100 actions which are subject to the recall and have not had their trigger assembly replaced should be returned to the factory. The actions with new trigger assemblies have an "O" on the flat surface at the rear of the receiver.

(Drawing)

1978 MODEL 600 RECALL INFORMATION

In 1978, all Remington Models 600 and 660, and Mohawk 600's (except those with a serial number starting with an "A") were recalled for trigger assembly replacement.

Rifles which have not had their trigger assembly replaced should be returned to the factory. The new/replacement trigger assembly has a "V" on the left side of the trigger up near the trigger plate.

(Drawing)