

To J. P. LINDE - F. E. MARTIN  
From A. A. HUGICK

Date May 12, 1977

Two years ago the XP-100 bolt plug and safety assembly designs were reviewed due to pending impact test of exposed hammer — striker assemblies. The safety has been modified with thumb piece material change — BUT — bolt plug changes have not been implemented. Abuse of the M/600 bolt plug for eliminating an exposed striker should be implemented as soon as possible.

AAH:bd  
Measurement/Test Lab  
Ilion Research Division

Copies to : C. B. Workman  
File

DON'T BE SORRY — BE SAFE

CC: C. B. WORKMAN  
FILE

DON'T SAY IT — WRITE IT

To J. P. LINDE - F. E. MARTIN  
From A. A. HUGICK

Date 5-11-77

TWO YEARS AGO THE XP-100 BOLT PLUG AND SAFETY ASSEMBLY DESIGNS WERE REVIEWED DUE TO PENDING IMPACT TEST OF EXPOSED HAMMER-STRIKER ASSEMBLIES. THE SAFETY HAS BEEN MODIFIED WITH THUMB PIECE MATERIAL CHANGE — BUT — BOLT PLUG CHANGES HAVE NOT BEEN IMPLEMENTED. ABUSE OF THE M600 BOLT PLUG FOR ELIMINATING AN EXPOSED STRIKER SHOULD BE IMPLEMENTED AS SOON AS POSSIBLE.

DON'T BE SORRY — BE SAFE