

Illion Research Division

May 20, 1977

MODEL 700 SAFETY EVALUATION

Serial No. 6859218

.270 Win.

J. Schiro

1. Safety lever is hitting bolt plug and top of stock.
2. Bright spot on bolt plug.
3. Slight galling on cocking cam on bolt body.
4. Trigger pull taken across comb cuts - 5#.
5. Firing pin head lines up with detent on bolt body.
6. Adjustment screws still glued.
7. Free oil on metal parts.
8. Lots of free oil on bolt stop.
9. Fire control housing full of free oil.
10. Sear surface sharp.

F. E. Martin/nl