

700 Classic - 243 cal.

11:20 AM
12-19-78

A6699899

Dent in stock left side near rec. right screw.
Bar string stuck in too far cracking wood.
Bolt finish not compatible.
Barrel contacts stock right side
Brass reinforcing pin protruding

A6699811

Bolt finish not compatible
Brass reinforcing pin protruding.
Dent in barrel over chamber.
Checkering over-run. - border does not clean up.
(fore-end panels).

A6699041

Bolt finish not compatible
Poor fill at reinforcing screw.
Mark on barrel from gun trucks.
Scratches on barrel.

A6699689 - ~~689~~

Bolt finish not compatible.

A6699023

Bolt finish not compatible
Brass reinforcing screw protrudes.
Checkering over-run. Barrel did not clean-up
(fore-end). Dent in stock Mark on toe of stock
from gun trucks
No pressure on bolt rod.

(2)

A 6699882

Poor cut at pod. Uneven.

Bolt finish not comparable.

Finish marks in stock

Excess finish at rear of eye. port on stock.

Rear sling screw too deep. wood chipped.

A 6699871

Bolt finish not comparable

Dent left hand side of stock

Excess finish along left side of stock.

Bolt release latch binds.

Dent in right side of trigger housing caused by screw driver

A 6699853

Bolt finish not comparable.

Off center sanding at fore-end tip.

Checkering over-run. Guard does not clean up