

3-3, 87

# IMPORTANT MESSAGE TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

Owners of the above guns should contact one of the following gunsmiths:

In Honolulu	In Honolulu	In Honokaa
Hon'sport, Ltd.	The Thom Company, Ltd.	Ka Pu Kapili
1365 Colburn Street	King & Smith Streets	P.O. Box 745
Honolulu, Hawaii 96817	Honolulu, Hawaii 96817	Honokaa, Hawaii 96727
(808) 833-3026 or	(808) 538-6764	(808) 775 0244
(808) 949-5591		

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.