3.3,90

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

Owners of the above guns should contact one of the following gunsmiths:

In Anchorage Howard's Gun Shop 528 Fifth Avenue (907) 272-4570

In Anchorage Bill's Gun Shop 8729 Lake Otis Parkway Anchorage, Alaska 99501 Anchorage, Alaska 99507 Fairbanks, Alaska 99701 (907) 349-1312

In Fairbanks Dixon's 261 College Road (907) 456-8742

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.

For Field Service

800 Enterprise Message Receiving Center

National Data Corporation Atlanta, Georgia

1-404-329-8527 or 8528

L157 #181

· Numbers for Gun Owners to Call:

Residents of Georgia: 800-282-1333 Operator #61

All Others: 800-241-8444 Operator #61

3-3,112

IMPORTANT MESSAGE TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a scrial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

Remington recommends that prior to any further usage of guns included in the recall, they be inspected - and modified if necessary. To obtain the name and address of the nearest Remington Recommended Gunsmith (who will perform the inspection and modification service free of charge), phone one of the following numbers:

In all states except Connectiont (toll free):

-1-808-243-2870

800-291-8444

من برسره المرام. In Goisections (Loll free):

1-600-972-9379

830-962-1333-222 3001

In Canada (collect):

519-621-7271