


TEST FOR 600 SAFETY FUNCTION

1/29/75 CP.

CHECK FOR NO AMMUNITION!

1. ACK RIFLE, CLOSE BOLT AND PUSH SAFETY BACK TO ON SAFE.
2. PULL TRIGGER - NO CLICK, TRIGGER RETRACTS.
3. PUSH SAFETY FORWARD ABOUT HALFWAY - TRY TRIGGER AGAIN - NO CLICK, TRIGGER RETRACTS.
4. PUSH SAFETY FORWARD SLIGHTLY.
 - a. SAFETY SHOULD SPRING FORWARD TO OFF. FIRING PIN REMAINS COCKED.
5. IF SAFETY DOES NOT SPRING FORWARD REPEAT STEP NUMBER 4.
6. REPEAT TEST 3 TIMES

DESCRIPTIVE INFORMATION



ENLARGED VIEW OF
DEAR-CONNECTOR
CLEARANCE.

FIGURE 2

PUSH CONNECTOR UPWARD HERE

FIGURE 1

PART NAME _____ COOLANT _____
TYPE "SCREWDRIVER" TEST & ASSEMBLY
CUSTOMER REPAIR

SET UP TIME _____ MODEL No. 700 & 600
MACH. IIR9 _____ DEPT. No. _____
MACHINE

OPER. No. _____
PAGE 2 OF 3