REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

PETERS

J. H. CARTER

Does Arms Service agree?

RIUL

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"\_

copies & Dennie + Don.

Ilion, New York May 21, 1979

Dry comments?

Jack

OK gerdienne f.

TO:

Remington.

TIMD

R. L. HALL 5-21-7

5-22.79

FROM:

J. P. LINDE JPL

SUBJECT: REPAIR OF MODEL 721-722 TRIGGER ASSEMBLIES

Research has made the following recommendations to modify a Model 700 Trigger Assembly to fit the obsolete Model 721-722:

- (1) Bend finger piece on Trigger to a tighter radius so it will clear Trigger Guard. Bending fixture available in Customer Repair.
- (2) Alteration to Safety Lever Assembly which requires reshaping lever to fit contour of Receiver and grinding clearance on side of safety button. Customer Repair has a bending fixture fabricated in the Model Shop and can readily alter Safety button.
- (3) The Stock has to be altered in two places to provide clearance for lever operation. Minor wood removal operation.

To insure control of this modification to the Trigger Assemblies and Stock, Product Engineering will prepare a writeup, samples, and the necessary gages to perform the required operation. The writeup will also include bench testing the completed rifle for such items as Bolt Release operation, Trigger clearance, and Safety Lever clearance.

JPL:eb