

25 NO. 25 EYE EARL
25 NO. 25 EYE EARL

METALLIC SILHOUETTE - PISTOL
XP-100 CALIBER 308 WIN ENDURANCE
JULY 1979 MEAS/TEST LAB.

1	2	3	4	5	6	7	8	9	10	11	12	13
TOTAL FIRE	RECOIL FIXTURE TEST SET-UP	SEAR LIFT SAFE ON	SEAR LIFT NULL	SEAR ENGAGEMENT	LUG AT REAR POSITION	LUG @ BOTTOM POSITION	BOLT ASSEMBLY	STOCK STOCK	TEST DATA STOCK	FRONT SIGHT	REAR SIGHT	COMMENTS
Range		INCHES	INCHES	INCHES	INCHES	INCHES	No.	NUMBER	CONDITION			
1 1000		.0110	.009	.0171	.0029	.0051	#1	#1	OKAY	OKAY	OKAY	6-15-79 EFM
2 100		.0128	.009	.0178	.0029	.0052	#1	#1	JOINTS OKAY	OKAY	OKAY	6-21-79 EFM
3 400		.0107	.009	.0186	.0029	.0052	#2	#2	OKAY	OKAY	OKAY	6-26-79 EFM
4 500		.0103	.009	.0172	.0027	.0051	#3	#3	OKAY	OKAY	OKAY	6-26-79 EFM
5 1000		.0105	.009	.0174	.0028	.0050	#3	#3	OKAY	OKAY	OKAY	6-27-79 EFM
6 1500	FIXTURE - TABLE	.0105	.0085	.0185	.0019	.0033	#3	#3	CRACKS	FAILED	OKAY	6-28-79
7 1500							#4	#4	OKAY	OKAY	REMOVED	7-3-79 A.A.H.
8 2000	FIXTURE - TABLE	.01075	.009	.0184	.0020	.0047	#4	#4	OKAY	OKAY	OKAY	7-11-79 A.A.H.
9 2000							#5	#5	OKAY	OKAY	OKAY	7-12-79 A.A.H.
10 2200	FIXTURE - JASK						#5	#5	FAILED	OKAY	OKAY	7-13-79 A.A.H.
11 2200							#6	#6	OKAY	OKAY	OKAY	7-13-79 A.A.H.
12 2670	FIXTURE - JASK						#6	#6	FAILED	OKAY	OKAY	7-16-79 A.A.H.
13 2670							#7	#7	OKAY	OKAY	OKAY	7-16-79 NY/SH
14 2800	FIXTURE - JALIC	.010	.0085		.0030	.0065	#7	#7	W/ SPLIT	OKAY	OKAY	
15 2800	EXTRA BULMERS ADDED											
16 2700	" "						#8	#8	OKAY	OKAY	OKAY	7-17-79
17 3100	" "	.010	.007	.0258	.0040	.0081	#8	#8	OKAY	OKAY	OKAY	
18 3300	" "	.013	.0083	.0208	.0028	.0054	#8	#8	OKAY	NOT SPLIT	OKAY	7-18-79
19												
20												
21												
22												
23												
24												
25												
26												
27												
28												
29												
30												
31												
32												
33												
34												
35												
36												
37												
38												
39												
40												

(C) WELD JOINT SPLIT - POOR / NO JOINT ADHESION [TRIGGER GUARD, FRONT SIGHT, REAR SIGHT DIAMETER]
(B) BOLT HANDLE FAILURE DUE TO CONTACT WITH RECOIL FIXTURE
(A) STOCK FAILURE OCCURRED WHEN RECOIL FIXTURE MEASURE STAMP FAILED