

RECEIVED SEP 18 21 43

REMARKS STRD

BOUWOOD AA22657

ATTENTION JANET MURPHY

RE ORDER NUMBER 3154/S MODIFICATION REQUIRED BY COMMONWEALTH
CUSTOMS ON XP100 AS FOLLOWS:

- 1 EXTERNAL LOCK NUT REQUIRED ON TRIGGER SEAR BLOCK STOP SCREW

17053.

Cannot get nut on & clean trigger lock.

- 2 TRIGGER PULL TO BE 4LBS PLUS.

Rev Speed 1 1/2 - 2 3/4

REQUIRED URGENTLY PLEASE ADVISE EXPECTED SHIPMENT DATE BY
AIRFREIGHT DELIVERY.

REGARDS ROSS LEVINSOHN

*Called Janet 9/27/79
& gave her above info
she will get back to us.*

RECEIVED

SEP 20 1979

BOUWOOD AA22657

19.9.79

JANET MURPHY

REMARKS STRD