

REPAIRS

M1700 BDL PRESS STOCK

Red Dye Test for Functioned Stock

10-26-79

C.J. Sweet

	1	2	3	4	5	6
	FUNCTION -					
	= 8					
1		①	Web cracked at			
2			reinforcing screw			
3						
4		②	Crack at Recoil			
5			lug location			
6						
7		③	Dye absorbed			
8			all over.			
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						