

## **REMINGTON M/710 NON-ISS BOLT PLUG** DAILY TEST DATA SHEET

## TRACKING # TLW1349 **PROJECT # MAYFIELD SUPPORT**

## BARBER 22 06r0007369

			ROUNDS	SAT START-	
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
J. Sims	12/5/03	INITIAL HEADSPACE	001		
J. SIMS	12/5/03	PROOF TEST		1	
J. Sims	12/5/03	HEADSPACE AFTER PROOF			
J. Sims		FIRING PIN INDENT	.021 .021 .019		
	1	TRIGGER/SEAR ENGAGEMENT	eng. 0712 0305, 03/1 duz. /Sar 1,14. 0187/18301 019, 0207.	0204.020	Ann - , 0206
BL/ JS	12-8-03	TRIGGER PULL	4.395 4.180-4.512- Aug 4.462 - Set, 4022		<u> </u>
J. Sims	12/8/03	JACK FUNCTION TEST	Stot chilling	40	41
		SETUP FOR SAAMI TESTING	Torque mous 25 in the / Scape Yoin Ks / Tak down Exercis Top Yoin 16 - La	Re ESiak	^
Bilee	12-8-03	Take dow sense	Center take downscrew steined	.	1 III.
BL/33		SAAMI ROTATION W/SCOPE	Pass Rolation This	saw 3	HOULD NO
BLIJS		Remeasure	engagement regenus 1	V	
BL 1.7.5		SAAMI JARR-OFF W/SCOPE	Diss IDF ATT	Subrec	tel to SA
B1175	12-9-03	Re marsin ne			
BL155	12-10-03	SAAMI DROP W/SCOPE	Fail drap wiscope * Note Balow * Jar-off	Rotati	mor dra
BLIJS	11/0 03	Remansare	engagement - tropper pall with as	tripped	takedown
BL. JJS	12-10.03	RESET TO STD. SPECS.	MSET CAS. 0222, 022, 025 AVG. 022	,, ,	Screwto
			Trigger Vall 4226-4.385-4.349-4.426-4.388- Avg 4	.475	(nf.
					SAT
					12/19/1
		Note -	This Can had the center take down screw		101110
			hole threads stripped out & the screw would		
			not stay in. There The drest this and		
			Fied on the balled horizontal, bottom down		
			drop. Upon investmention of this with the center		
			take down screw stringed it allowed the stock		
			to Flex more and allow the action / bott assy.		
· · · · · · · · · · · · · · · · · · ·	· ·		To pull away Flom the fire control which was		
		· · · · · · · · · · · · · · · · · · ·	held in the stock by the real take down screw.		
			This could also be duplicated in a heach Vise, which		
		· · · · · · · · · · · · · · · · · · ·	was demonstrated multiple times both with safe		
			On and the safe st. The could not be		
			do so an that had all & take dry share	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
				-	
			Hand Jours		
			installed and Tight.		
	·				
			No. 1		

ET33857

Land and the second