

10/15/80

Hammer marks on- 7400's now running at 9"/min - why?

- Harper Buff - color in Sept 79

color 1952 in Sept 79

** - Harperbuff — could be a problem

Phil

Do we have
a strength
problem

- New uprator?

- method of cooling - "H" from US TubeHammer Marks - on 243 & 7mm