


VISUAL INSPECTION

A-19

The strands
had to be
cut off.



Gap between
Recoil Pads
and stocks.



Some large knots
on the stocks.

