

10.81

WAW

MONTHLY REPORT
WEEK OF 10-7-91

PRODUCTION HAVING TROUBLE
WITH CREEPY TRIGGER PULLS
OVER PREVIOUS TWO WEEKS.

WE FOUND THAT ALBOT
ONE OF TRIGGER ASSEMBLERS
HAD EXCESSIVE ENGAGEMENT
ON 6 TR. ASS'YS SET
ASIDE AS THE WORST
ONES.

I SUGGESTED TO B. VANSICKLE
THAT HE HAVE EACH
TRIGGER ASSEMBLER CHECK
HIS OWN PARTS AND
CORRECT THEM, ALSO, BE
SURE TRIGGER IS FIRMLY
SEATED AGAINST ENGAGEMENT
SCREEN AS ENGAGEMENT
ADJUSTMENT IS MADE.

(SHOULD BE EXCESS
TRIGGER SPRING FORCE
AT THIS POINT OF
OPERATION).

ALSO, TRY CORRELATED
TRIG. ASS'YS IN GUNS TO
VERIFY THAT THIS WAS CAUSE
OF COMPLAINTS.

ALSO; TRY SOME ONE'S ASSUMPTION