

100 Rd. Jack Function Test Guns B-21 to B-30
TLW0300Z
11/20/00

This is a 100 rd. Basic Jack Function Test performed in the Function & Casualty Range, using the std. Remington test jacks.
Only Remington ammo was used, 20 rds. ea. of 5 types.

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-21	71001613	Rem. L30062, 150 GR. MC	M03G B1	0
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	0
		Rem. R30064, 180 gr. SP	K28G B 3713	1 STEM LOW
		Rem. R30065, 180 gr. PSP	K04 UA7926	0
		Rem. R30067, 220 gr. SP	M06N B26	2 STEM LOW (FOLLOWER BINDING)
Technician-	Philip Reesor			
Comments Noted-	stopped test @ 88 rds. because of magazine follower binding at top & causing stem lows			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-22	71001623	Rem. L30062, 150 GR. MC	M03G B1	0
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	1 mag released & dropped down
		Rem. R30064, 180 gr. SP	K28G B 3713	0
		Rem. R30065, 180 gr. PSP	K04 UA7926	2 mag released & dropped down
		Rem. R30067, 220 gr. SP	M06N B26	0
Technician-	Philip Reesor			
Comments Noted-	Magazine is difficult to remove from gun, seems to bind easily.			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-23	71001632	Rem. L30062, 150 GR. MC	M03G B1	0
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	0
		Rem. R30064, 180 gr. SP	K28G B 3713	0
		Rem. R30065, 180 gr. PSP	K04 UA7926	0
		Rem. R30067, 220 gr. SP	M06N B26	0
Technician-	Phillip Reesor			
Comments Noted-	Grip cap came off during test.			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-24	71001634	Rem. L30062, 150 GR. MC	M03G B1	0
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	0
		Rem. R30064, 180 gr. SP	K28G B 3713	1 stem low
		Rem. R30065, 180 gr. PSP	K04 UA7926	0
		Rem. R30067, 220 gr. SP	M06N B26	0
Technician-	Phillip Reesor			
Comments Noted-	Magazine difficult to remove. Bolt very hard to pull rearward one time.			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-25	71001643	Rem. L30062, 150 GR. MC	M03G B1	0
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	0
		Rem. R30064, 180 gr. SP	K28G B 3713	0
		Rem. R30065, 180 gr. PSP	K04 UA7926	mag box bottom came off (stopped test)

ET34256

Confidential - SHARPER - 5.22.06r0007768 Order

Williams v. Remington

Rem. R30067, 220 gr. SP M06N B26

Technician- Phillip Reesor

Comments Noted- Magazine is difficult to remove from gun, seems to bind easily.
Magazine box bottom came off @ 62 rds. (stopped test)

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B26	71001647	Rem. L30062, 150 GR. MC	M03G B1	
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	
		Rem. R30064, 180 gr.SP	K28G B 3713	
		Rem. R30065, 180 gr. PSP	K04 UA7926	
		Rem. R30067, 220 gr. SP	M06N B26	

Technician-

Comments Noted-

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-27	71001724	Rem. L30062, 150 GR. MC	M03G B1	
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	
		Rem. R30064, 180 gr.SP	K28G B 3713	
		Rem. R30065, 180 gr. PSP	K04 UA7926	
		Rem. R30067, 220 gr. SP	M06N B26	

Technician-

Comments Noted-

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-28	71001760	Rem. L30062, 150 GR. MC	M03G B1	
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	
		Rem. R30064, 180 gr.SP	K28G B 3713	
		Rem. R30065, 180 gr. PSP	K04 UA7926	
		Rem. R30067, 220 gr. SP	M06N B26	

Technician-

Comments Noted-

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-29	71001782	Rem. L30062, 150 GR. MC	M03G B1	
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	
		Rem. R30064, 180 gr.SP	K28G B 3713	
		Rem. R30065, 180 gr. PSP	K04 UA7926	
		Rem. R30067, 220 gr. SP	M06N B26	

Technician-

Comments Noted-

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-30	71001789	Rem. L30062, 150 GR. MC	M03G B1	
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	
		Rem. R30064, 180 gr.SP	K28G B 3713	
		Rem. R30065, 180 gr. PSP	K04 UA7926	
		Rem. R30067, 220 gr. SP	M06N B26	

Technician-

Comments Noted-

ET34257

Confidential - ~~SECRET~~ - 5.22.06r0007769 Order

Williams v. Remington