

IX. Malfunctions Continued

<u>Remington M-700</u>	<u>No. of Rds.</u>	<u>Malf.</u>	<u>Rate</u>
30-06 Cal. ADL #B625032	0-500 <u>501-1000</u> 1,000	None None None	0% 0% 0%
243 Var. BDL #B6270650	0-500 <u>501-1000</u> 1,000	None None None	0% 0% 0%
7mm Rem. Mag. #B6245077	0-500 <u>501-1000</u> 1,000	1 - Action Bind 10 - Shell JumpsMag. None 11	2.2% 0% 1.1%
<u>Three Rifle Total</u>	<u>3,000</u>	<u>11</u>	<u>0.4%</u>
<u>Ruger M-77</u>			
30-06 Cal. #73-95020	0-500 <u>501-1000</u> 1,000	None 1 - Stem Low 1	0% 0.2% 0.1%
243 Var. #74-00086	0-500 <u>501-1000</u> 1,000	None 1 - Stem Low 1	0% 0.2% 0.1%
7mm Rem. Mag. #74-24449	0-500 <u>501-1000</u> 1,000	None None None	0% 0% 0%
<u>Three Rifle Total</u>	<u>3,000</u>	<u>2</u>	<u>0.2%</u>
<u>Smith & Wesson M-1500</u>			
30-06 Cal. #PN01129	0-500 <u>501-1000</u> 1,000	1 - Stem High None 1	0.2% 0% 0.1%
243 Cal. #PN11952	0-500 <u>501-1000</u> 1,000	None None None	0% 0% 0%
7mm Rem. Mag. #PN02081	0-500 <u>501-1000</u> 1,000	None None None	0% 0% 0%
<u>Three Rifle Total</u>	<u>3,000</u>	<u>1</u>	<u>0.03%</u>