

VISUAL INSPECTIONS

Machining Marks
and Poor Color to
All Bolt Heads.



Clear Brealline
Between Jewel
and Color.



Lack of Stain
Under (Kle)
Finish.

