

VISUAL INSPECTIONS

The Strands had  
to be cut off.

Gap between  
Recoil Pads  
and stocks.

Some large  
Knots on the  
stocks.

