

3/24/83

BERZBURG. 24 MAR 83 SN: 03/140

3. E. GERRAL

RE: NEW SAFETY DEVICE ON MOD 700 AND MOD SEVEN

WE HAVE APPARENTLY A PROBLEM WITH THE SALES OF MOD 700 AND MOD SEVEN WITH THE NEW SAFETY SYSTEM (= BOLT CAN BE OPENED WHEN SAFETY LEVER IS ON "SAFE" POSITION) IN SCANDINAVIA. SWEDEN, NORWAY AS WELL AS FINLAND REPORTED THAT CONSUMERS DO NOT ACCEPT THIS NEW VERSION AS AN IMPROVEMENT. THEY WANT TO GET THE GUNS WITH THE OLD SYSTEM (= BOLT CANNOT BE OPENED IF SAFETY IS ON "SAFE" POSITION).

REASON FOR THIS IS THAT HUNTERS ARE AFRAID THAT THE BOLT CAN BE OPENED WHEN CARRYING THE GUNS OVER THE SHOULDER AND HITTING BENCHES OF TREES WHEN WALKING OR SKIING THROUGH THE WOODS. THEY HAVE APPARENTLY EXPERIENCE WITH THIS.

PROBLEM CAN PROBABLY BE SOLVED BY REPLACING THE NEW SAFETY ASSEMBLY WITH THE OLD SAFETY ASSEMBLY (LONG LEVER) INDEX 26565. THIS CAN BE DONE BY THE GUNSMITH OF THE DISTRIBUTORS.

PLEASE ASSIST US AS FOLLOWS:

1) CHECK WITH ILION IF THIS IS A SOLUTION.

2) IS THE SAFETY ASSEMBLY OF MOD 700 AND MOD SEVEN THE SAME?

3) WILL THE GROOVE IN THE REAR OF THE BOLT (IN WHICH THE LONG LEVER OF THE OLD SAFETY ASSEMBLY FITS) STILL BE MADE IN THE NEW GUNS (THE GROOVE IS STILL IN THE NEW GUNS WHICH WE HAVE RECEIVED).

YES
for John Groves

4) IF ABOVE IS YES: PLS PUT IN AN ORDER FOR 2000 EACH OLD SAFETY ASSEMBLIES PART NO. 26565 FOR NO CHARGE DELIVERY AND RETURN BY END OF THE YEAR THE REPLACED NEW ONES.

THANKS FOR YOUR ASSISTANCE.

RECORDED
FORST TREBATTI

John Banks

8

65566 REMARK DE

International Telex Western Union International Inc. International Telex