

Remington.



*mailed out
4/14/83*

REMINGTON ARMS COMPANY, INC.

TELEX
964-201
STRATFORD, CT

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

939 BARNUM AVENUE
P.O. BOX 1939

TELEPHONE
203-333-1112

BRIDGEPORT, CONNECTICUT 06601

TO OUR GUNSMITHS:

Remington Arms Company has discovered a problem may develop with the Model Seven rifle and is requesting your assistance updating rifles currently in the field.

We have discovered that if a Model Seven rifle is disassembled after it leaves the factory, it is possible for the rifle to be reassembled incorrectly, producing off-center trigger alignment that might cause subsequent malfunction of the trigger and accidental firing of the rifle.

Since a rifle may be disassembled at any time in the future for one of several reasons, we wish to update all Model Seven rifles with a preventative modification that eliminates the possibility of such incorrect reassembly.

We are currently contacting all distributors, dealers and consumers who have purchased Model Seven rifles requesting they have their guns updated by a Remington Warranty Gunsmith in their area. Remington will provide a list to those parties who our records show possess Model Sevens.

IMPORTANT: To assist you, we have attached a detailed explanation of the updating process. Please review carefully before beginning any repair.

In the near future, you will be receiving a no-charge quantity of Model Seven updated trigger assemblies. After the rifle has been updated, the following procedures must be followed.

- (1) Prepare New Gun Repair invoice being sure to provide the customer name and address (including zip code) and the serial number of the rifle. (Additional no-charge invoices may be obtained by writing R. L. St. John, Remington Arms Co., Inc., Arms Service Division, Ilion, New York 13357.)

- (2) Make a charge not to exceed \$20.00 per gun (includes labor, postage and handling).
 - (3) Enclose replaced trigger group with your invoice. We will be unable to pay invoices until replaced trigger groups are received.
 - (4) Mail to Remington Arms Company, Inc., Arms Service Division, Ilion, New York 13357, for reimbursement. Mark envelope - Model Seven Update.
- o For technical assistance, call Arms Service at 315-894-9961.
 - o For all other Model Seven information, you may use our toll free number - 800-243-2953 (8:00 - 4:30 EST).

R. L. St. John

R. L. St. John
Supervisor, Field Service

RLSTJ/lc