

I

4/14/83

4-11-83

Firearms Product Manager
 Remington Arms Co, Inc.
 939 Barnum Ave.
 Bridgeport, Conn. 06602

J. A. S. Simon
 Please handle

Thompson
 Full

RECEIVED

APR 18 1983

J. A. S. Simon

Dear Sir:

I purchased a 788 Remington rifle in
 .243 caliber on 1-12-82, serial No.
 B6096449.

I am satisfied with its accuracy, but
 the safety seems sloppy. It slips to
 the firing position very easily, sometimes
 even accidentally. The biggest trouble is
 the cartridges hit the scope on ejection
 and fall back into the chamber.

I have had it to the gun smith
 school twice at the Vo Tech in Pine
 City, Minn. They put higher scope
 mounts on it and checked it all over
 for burrs and etc. They still hit
 the scope. I have talked to several
 people with 788's and they all have
 the same problem.

/

II

I know it is a low priced rifle, but it should work. Especially, with a name like Remington, I expected quality. I tried to trade it for a higher priced rifle and the dealers all know about the problems and do not want any used 788.

Is there any fix to this rifle, or should I throw it away and buy a different brand.

Sincerely,
David Mason
Route 1
Hinckley, Minn. 55037

David Maser
Route 1, Minn.
Hickley, 55037



Firearms Product Manager
Remington Arms Company, Inc.
939 Barnum Avenue
Bridgeport, Connecticut
06602