

GUNSMITH CALL REPORT

44-241-82

Reporter Donald McIlwaine

Shop Name Sportswest-Div of Ray's Save Corp Gunsmith's Name Daniel Cowen

No. & Street 502 South Third City Renton State Washington Zip 98055

Gunsmith on Premises? YES If not, give address below:

Gunsmith's Address No. & Street City State Zip

Recommended List (X) Open Acct. (X) % Disc. 30% Dealer (X) Large (X) Small ()
New Gun Repair

PERSONS INTERVIEWED and POSITION:

1. Daniel Cowen Gunsmith (2)
3. (4)

SPECIFIC PROBLEMS ENCOUNTERED:

1. M700 still very heavy trigger pulls from factory.

GENERAL DISCUSSION

No special problems. Lots of rebluing work, again because of the geographic location.

Dan did bring up the point that we are still sending out M700's with very heavy trigger pulls, 7-7½ pounds or heavier. This shop performs all the repair work for the chain of Sportswest stores in the north west area. Since the volume of stores sell a large number of M700's Dan receives several sent in from the other stores just to have the trigger pull lightened to the 3-4 pound range. This fact disturbs me because I wonder how many do it yourselves adjust their own triggers and do it improperly perhaps by reducing the sear engagement.

PLAINTIFF'S
EXHIBIT

3127

AL 0024034