

Rev. 2-19-61

I. NO GUN EXAMINATION REPORT NUMBER: 500 MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 19506
 OUTSIDE WORK: SCOPE BASE ADDED DATE: 7-30-81
 FIRE ARM TYPE: NOT KNOWN FROM: H.G. BENTLIN
2646 JACKSON PK.
FALLS CHURCH VA
 & CONDITION: _____ GUN #: 223209
 PROOF: (REP) INSP.: 9 TEST: 87 CODE: ON = 7-66
 HEADING: OK GA./CAL.: 243
 BREACH OPENING: OK CHECKED BY: M-HARDY
 RECOIL SHOULDERS: OK APPROVED: PH 9/1/81
 CHAMBER: OK APPROVED: PH 9/1/81
 TEST: _____ APPROVED: PH 9/1/81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: PH 9/1/81

OLD STYLE FIRE CONTROL. SLIGHT DENTS IN WOOD

COMPLAINT: FIRE WHEN SAFE IS RELEASED, AT TIMES

INCIDENT: _____

COMMENTS: _____

'lean - safety cam sticks in downward position,
because of accumulation of dirt & oil. Clean & return
to customer. clean Bolt & Firing Pin Head, as has
and on it also.

Send new instruction manual to customer.