

Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: 530MODEL: 700 BDLGENERAL CONDITION: FAIRR #: 24180OUTSIDE WORK: S/REMOVED, SCOPE MOUNTS ADDEDDATE: 10-9-81TRIG & CONNECTOR REMOVED AS ISFROM: BILLY W. SWEAT
PT. 22 BOX 166A
ALLEN TON TEN.FIRE ARMS TYPE: NOT KNOWN

& CONDITION:

GUN #: A6376164PROOF: 11 INSP.: 123 TEST: 64CODE: RI-11-76READING: OKGA./CAL.: 6MM REMBREECH OPENING: OKCHECKED BY: M-HA 900RECOIL SHOULDERS: OKAPPROVED: 9/28/81CHAMBER: OKAPPROVED: 10/2/81TEST: CHECKED FIRE PIN PROTRUSION, OKAPPROVED: 10/2-81

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED:

TRIG. CONNECTOR BROKENCOMPLAINT: FIRE WHEN TAKEN OFF SAFETY

INCIDENT:

COMMENTS:

Please replace fire control - no charge