

PHONE NO. 343-6172

THE TRADING POST

4147 WEST MAIN STREET ROAD, ROUTE #5
BATAVIA, N. Y. 14020

RECEIVED

AUG 30 1983

August 26, 1983

J.A. STEKL

*Send copies to*Remington Arms Company, Inc.
Ilion, NY 13357*J.P. LINDE*
C.B. WORKMAN
W.A. WALKER } *Please*
advise

Gentlemen:

We are experiencing a serious problem in our shop in trying to mount Redfield Jr. Bases, Rings, and Scopes to Remington 700 BDL and ADL rifles.

The Redfield bases made for your 700 series rifles will not permit vertical adjustment of the Redfield scopes (which have 48 to 52 inches of adjustment.) When all the adjustment has been used, the rifles still shoot high; a shim must be placed under the front of the base to lower the impact point.

We phoned the Redfield factory and they claim their bases were/are made in strict compliance with the specifications furnished them by Remington. ~~They feel Remington rifles made after 1975 have been manufactured to different specifications as regards the receivers.~~


Please advise us immediately of your opinion of this problem. We cannot understand how two companies the caliber of Remington and Redfield could be at odds in this manner. We are losing sales of both Remington rifles and Redfield scopes because of this problem.

Thank you,

Earl Haddix
Earl HaddixREMINGTON ARMS CO.
RECEIVED

SEP 1 1983

FIREARMS RESEARCH DIVISION

WHOLESALE SHOOTER'S SUPPLIES • RELOADING SUPPLIES • GUNS • AMMUNITION • OUTDOOR CLOTHING
FISHING TACKLE • EVINRUDE MOTORS • MARINE EQUIPMENT