SAFE "OFF - ON" FORCES

PROCEDURE FOR MEASURING SAFE "OFF - ON" FORCES

1. <u>General</u>

To measure Safe "Off - On" forces on firearms not manufactured by Remington Arms, Consult Lab Supervision.

1 A. Equipment Needed (Fig. 4 - 9)

- Push pull gauge.
- Test Procedure Sheet.
- Work Bench with a Gun Saddle.



Figure 4-9

- 5 -

....