

~~John~~
A

11/200 Sea Safety Com

Potential customer complaints from insufficient charge
material analyzed from 6/13/78 - 1/31/80

Possible complaint

11/1
2/10 5

- 1) Delayed firing
- 2) Discharge when bolt handle raised
- 3) Discharge without pulling trigger
- 4) Accidental discharge
- 5) Trigger - Safety malfunction
- 6) Misfire

7

7

2

9

1

2

28 Total

PLAINTIFF'S
EXHIBIT

3137

AL 0025778