

2-7-84

RSM

XC 0405

150 PSP 20 OK

180 PSP 20 OK

180 SP 20 OK

Broke forward tip

Safe works hard to "on"

Safe works hard first time to "on" only (bind?). Then works ok. no positive detent.

Extractor appears twisted



150 PSP 20 OK

150 PSP 20 OK

Safety definitely seems to be binding on firing, when freed even after repeated dry firing is OK.

Not enough engagement in rear trigger guard screw, loosens

Trigger pulled on safe - can feel trigger rubbing on sear, resets 90% of time so safe can be moved to fire position. 10% sear trips trigger, safe can't be moved

Trigger pull very crisp, no perceptible motion before firing. Little, if any overtravel