



REMINGTON-ARMS COMPANY, INC.



SPORTING WEAPONS
TRAPS
POWDER METAL PARTS
ILION, NEW YORK
BRIDGEPORT, CONNECTICUT
LONOKE, ARKANSAS

MANUFACTURERS OF -
SPORTING FIREARMS, AMMUNITION
TRAPS TARGETS
ILION, NEW YORK 13357
TELEPHONE 512 54-9961

PETERS CARTRIDGE DIVISION
BRIDGEPORT, CONNECTICUT
TARGETS, ADA, OKLAHOMA
ATHENS, GEORGIA
FINDLAY, OHIO
CABLE—HARTLEY, BRIDGEPORT

August 30, 1984

Mr. Dick Key
P.O. Box 303
Mineral Bluff, Georgia 30559-0303

Dear Mr. Key:

Your letter of July 24, 1984 that was addressed to our Bridgeport, Connecticut facility, regarding the accidental firing you experienced with your Model 700 22-250 Rem. caliber rifle, serial number A6850932, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the nature you described, as it is not characteristic of the Model 700 rifle.

Generally, the type of malfunction you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or, from pressure being inadvertently applied to the trigger at the instant the safety is released.

Please, at your convenience, return the rifle via insured and collect transportation, to:

Remington Arms Company, Inc.
Attn: Mr. J.A. Stekl
Supervisor, Product Service
Ilion, New York 13357

Upon receipt, we will thoroughly examine the rifle and, if it is found to be factory faulty, we will assume responsibility for your unfortunate mishap.

Thank you for bringing this matter to our attention and for affording us this opportunity to be of service to you.

Sincerely,

J.A. Stekl
J.A. Stekl, Supervisor
Product Service

NOTE
(OVER)

JAS:tpg