

RECEIVED

Remington Arms Company, Inc.
Bridgeport, Connecticut

MAR 10 1955

J. A. STEKL

Dear Sir:

I am writing this letter in regard to a problem I have had with the bolt and safety action on my Remington model 700 BDL in the 30-06 caliber.

I have had the gun discharge while taking off the safety when I didn't have my finger in the trigger guard or near the trigger.

The first time this happened the gun was laying across the seat of my pickup and I got a large hole in the seat and another through the passenger door.

I have heard of other 700 BDL's with the same problem, and was wondering if there was a method for correcting this situation. If so, please send me the information necessary because I am otherwise very happy with the gun.

Very Thanks
Phil Hucker

P.S. My return address is

Phil Hucker
Box 25
Mount Valley, Kansas
67354