<u> and a second of the second o</u>

pennis:
When (if) rifle is received, forward to P.I.
Committee immediately.
JAS

bcc: E.F. Sienkiewicz J.R. Snedeker D.J. Sanita

February 23, 1983

Mr. Henry B. Fernandez, Jr. Asash Termite & Pest Control 1102 Clark Blvd.
Laredo, Texas 78040

Dear Mr. Fernandez:

Your letter of February 10, 1983 that was sent to our Bridgeport, Connecticut facility, regarding the accidental firings you have experienced with your Model 700 243 Win. caliber rifle, serial number A6373493, has been forwarded to this office for handling.

We were indeed sorry to learn of your having had a problem of the nature you described, as it is not representative of Remington quality, nor characteristic of the Model 700 rifle.

Generally, the type of incident you have described results from either improper adjustment of the trigger assembly outside our factory, foreign material, such as excessive lubrication, inside the trigger assembly, or, from pressure being inadvertantly applied to the trigger while the safety is in the "fire" position.

Please, at your convenience, return the rifle via insured and collect transportation, to:

Remington Arms Company, Inc. Arms Service Division Ilion, New York 13357

Upon receipt, we will have our technicians thoroughly examine your rifle and, if it is found to be factory faulty, any necessary repairs or other corrections will be made on a no-charge basis. If

February 23, 1983

-2-

otherwise, a repair quotation will be sent for your approval prior to effecting any repairs.

Thank you for bringing this matter to our attention, Mr. Fernandez, and for having afforded us this opportunity to be of service.

Sincerely,

J.A. Stekl, Supervisor Firearms Product Service

JAS: tpp

