

bxc: D.J. Sanita
Please clean rifle and install
new-style trigger assembly at
no-charge.
JAS

May 17, 1984

Mr. Dennis Vissering
SR Box 141
Michigan, Michigan 49861

Dear Mr. Vissering:

Examination has been completed on the Model 700 BDL 30-06 caliber rifle, serial number 6725148, that you returned to us a short time ago.

The returned rifle, which was produced in March of 1974, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had passed all our necessary tests prior to shipment from our factory.

Removal of the barreled-action from the stock revealed that the under-side of the barrel and receiver (including the trigger assembly) were coated with a combination of partially dried lubrication and dirt. This material was also visible on the internal parts of the trigger assembly. It is entirely possible that this accumulation on the trigger parts caused the malfunction you experienced.

As a gesture of customer good-will, we will give the rifle a thorough cleaning and, install one of our new style trigger safety assemblies that will allow the bolt to be opened with the safety in the "on-safe" position, at no-charge.

We trust that our handling meets with your approval, and thank you for allowing us to examine the rifle and report our findings.

Sincerely,

J.A. Stekl, Supervisor
Product Service

JAS:tpg