Report# 920431 17 Work Order# 481167 APPENDIX C ENDURANCE TOTAL MALF. MALF CALIBER SERIAL# SBC EDS BO DE JM DX SSM RDS **RATE** 338 Win C6671720 Ō 0 Ö 45 4000 4 41 Õ 0 1.13 .25 338 Win C6678193 22 3 0 0 0 0 0 25 10000 Ô .30 n 0 0 Ω 1 12 4000 7mm Wby C6678201 11 7mm Wby C6678174 1 20 0 4 Ð 2 0 27 10000 .27 300 Win C6671714 0 25 32 3 14 0 0 74 4000 1.85 3 0 25 10 4 0 .25 300 Win C6678188 0 в 10000 C6678192 7mm Rem 36 15 20 0 0 0 196 4000 125 4.90 C6678181 17 12 0 0 0 0 0 29 10000 .29 7mm Rem Ð 0 2506 C6678189 0 0 0 0 0 0 4000 0.00 2506 C6678195 0 0 0 0 0 0 0 0 10000 0.00 280 0 0 0 0 0 0 C6706176 0 0 4000 0.00 280 0 0 0 0 0 C6706177 1 0 1 10000 .01 C6706171 3006 0 0 0 0 0 0 0 0 4000 0.00 3006 C6671716 0 0 0 0 0 0 0 0 10000 0.00 0 0 270 0 0 0 0 C6706173 O 0 4000 0.00 .02 270 C6678194 O 0 0 2 0 0 0 2 10000 TOTALS 181 147 50 33 14 10 1 436 112000 **.**398 CALIBER SERIAL# ROUND COMMENTS C6671720 1540 Replaced Extractor and EDS problem cleared up. 338 WIN 3100 Fire Control was adjusted due to increased trigger pull. 338 Win C6678193 3 Replaced Extractor. 2000 First round feeding from Magazine(right side) will bind belt against belt on shell underneath. 4900 Replaced Extractor. 5100 Burnished chamber. 7mm Wby C6678201 START Bolt won't close over full Magazine. Bolt closes (cams) hard. mm Wby C6678174 1000 Bolt won't close over full magazine. 3000 Very hard to extract fired case. 4000 Burnished chamber to alleviate hard extraction. 300 Win C6671714 100 Magazine Follower staked by J. Ronkainen. 500 Old style, plated follower was installed to improve the jumping of shell from under the rail. C6678188 START Bolt won't close over full Magazine. 300 Win 200 Staked tab on Magazine Follower. 400 Replaced Extractor. 7mm Rem C6678192 100 Staked tab on Magazine Follower. 300 Staked tab on Magazine Follower. 300 Bolt closes hard over full Magazine. 7mm Rem C6678181 START Bolt won't close over full Magazine. 800 Trigger pull increased to 10 Ibs. 3300 Cleaned Bolt face. (EDS cleared up) 280 Rem C6706176 2000 Heavy bolt lift. 270 Win C6706173 200 J. Ronkainen staked Magazine Pollower to keep spring in correct position. 270 Win C6678194 1200 Trigger pull increased to 8.5-9 lbs. Moly-Kote found in Fire Control; Cleaned and readjusted to specification by production. NOTE: Bolt closes hard over full magazine caused by the center guard screw being too tight