## **BARBER - PRESALE R 0121121**

											DCR #	·	3	เบช	21		
DESIGN CH	IANGE	REC	QUEST	(DCR	)						Sheet		/	of			
PARTS LIS	<del>T CHA</del>	NGE	NOTICE	(PL	<del>CN)</del>	٠											
<del>-OR-</del> <del>PARTS-LIST-TRANSMITTAL</del>											nged E		Date				
								RED EJY RED EJY 1					1/28				
									Ori	ginati	ng Dat	:e	Trans	mitta	l Dat	te	
TRANSMIT	TAL of	- DR	AWINGS	7 <del>-111</del>	K 13-1	not	•						2 -	· 1 -	. 7-	7	
Model			Par	t Nan	ne /	<b>4</b>					Draw:	ing No	o.	Par	t No.		
540 XR	TR	166	ER HO	USIN	6 AS	SEM	BLY		1		C-14518			14518			
788		11		"		"				v	C-2	936	5	20	36 <i>5</i>		
541-5		/1		11		,,				/	C- 3	213	0	31	2130		
580 SERIES		11		11		41				`	D-2	901	5	2	9015		
Dwg. No.	Rev. l	No. Desi								Change							
C-14518	3		NOTE	ΑÛ	DED	70					EM. F	2R .	208" (	MIN.	SEAK	LIFT	
C-29365	19		,,		· •	.,				.,		.,		11	11	; +	
C-32130	2	<u> </u>	n		·	"	"		,			٠,	,,		l g	•,	
0-29015	21	レ	"	,	•		,,			1,		"	fi		4	<u>''</u>	
<u>-</u> ,																	
	<u> </u>											_			~		
Reason for Ch	ange:										0F						
	ukevi							ER	A	ND.	THE	SE A	R u	1HEV	<u> </u>		
711-6	SAF	ETY	15	ENU	ALE	<u> </u>									<u>v</u> .		
Diamanisian as	Donto o	- U-	nd (aboat	r bala	1												
Disposition of  Scrap		) Alt				nvento	rv								, ·-		
											•			====			
(PLCN) Use f	orm be	low i	f part nu	mber	is char	iged / a	add – u	sed, or	sup	ersede	d.	<del></del>	···			<del></del>	
	Drawing No.			Part No.				Part Name						<del></del>			
Current Listin	ıg														<del> </del>		
New Listing		<u> </u>															
Current Listing																	
New Listing																	
		NO	ΓE: Plea	se ma	rk you	r Parts	List to	agree	( )	)						<b>-</b>	
) Superseded	Part is	Obso	lete (che	ck dis	positio	n belo	w)										
( ) Use Up	)	( )	Scrap		( ) 5	Service	Repair		(	) Ot	ner Mo	del Us	se				
New Part is	: ()	Stee	1 ()	Powd	er Met	:al (	) Ass	embly	(	) W	ood	( ) F	urchas	ed	()(	Other	
APPROVED:	JP		131/77	C	f 2,	11/27	)	<u> </u>									

10327