	ANGE REQUE	est (DCR)					1		
OR			sted By		anged By	Date			
Фруисмафа		PRODUCTION		M	KEENEY	1-11-93			
TRANSMITTAL OF DRAWINGS/PARTS LIST OR					Origina		ate	<u>Transmit</u>	tal Date
PARTS LIST CHANGE NOTICE (PLCN)					1-11-93			3-8-93	
Model		Drawing No: Part No.							
Houer	PART NAME/LIST RECEIVER					1			are no.
XP-100					D-9		79:	3	
	 			····	<u> </u>	-			-
						-		-	
	 								
	 								
- 1-1-1-1	<u> </u>	 							
Dwg. NO.	Rev. No.	<u> </u>		SIGN CHANGE					
D-97793	2	Was Z	. 300						-
	 								
	 								
	 								
	-								
	<u> </u>	<u> </u>				·			
Classificat	ion of Cha	nge							
() Funct () Safet () Appea NOTE: Any	or all of	ge m Revision the above		equire approv	al of DO	R by			
Lab	Director	- New Prod	ucts Resear	ren					
() 0+1-0-									
() Other									
() Other						ND.	/	TONAMUNE	
() Other						AD DESIG	NER	SIGNATURE	
		-972 <u>93</u> X	Rev. 2:	2.380 Die					
Reason for (Rev. Z :		7 <i>62 4</i> 3				
Reason for (Change: D				ב אנגע מ				
Reason for (Change: D				n was				
Reason for (Change: D				- <u>648</u> 3				
Reason for (Change: D				n was				
Reason for (Change: D				n WAS				
Reason for (Change: D	ACE.			7 6483				
Reason for (Change: D	on Hand: (Check Below			2.30		78 COM	
Reason for (Change: D	on Hand: (Check Below	v)	() RD	2. 30 6589 At	tach	78 COM	TROL

DCR

Sheet

BARBER - PRESALE R 0121413