

Handy Single

A action guns use this model, outside of excessive pressure ammunition, as firing or blowing into the firing pin sticking forward.

[m/200. In your gun forward -

This was a problem some time ago when the reassembly operation was performed by the first assembler. If too much cement was put on the same handle, in the process of turning the housing to seat the screws on the opposite side, the excess cement would go between the side plates in the area of the rear spring. The procedure now is for this operation to be done by a sub-assembler who leaves the housing in one position until the cement dries. Then the housing is turned over, and the opposite screws cemented.

gabauer
11/29/75

PLAINTIFF'S
EXHIBIT

3170

1071
AL 0029692