Danner, Dale

From:

Reesor, Phillip K.

Sent:

Friday, December 15, 2000 1:39 PM

To: Cc:

Franz, Scott Danner, Dale

Subject:

RE: Slam Test CORRECTION

Correction to C-4 results, NO malfunction

From:

Sent:

Reesor, Phillip K. Friday, December 15, 2000 10:23 AM Franz, Scott

To:

Danner, Dale

Cc: Subject: Siam Test

Slam Test:

This was a 4 gun test, instructions consisted of shooting 20 round of live fire through each gun, closing the bolt smartly on every round.

Results:

There were no follow downs or inadvertent firings during this test.

Gun C-1, Bolt handle broke off while closing the bolt on round 15. This occurs at the end of the forward bolt movement and before rotation had started. The bolt was forward and emained in the unjocked position

Gun C-2, Bolt handle boke off while closing the bolt on round 2 Same as C-1

Gun C-3, Grip cap came off upon firing round 5.

Magazine box bottom came off upon firing round 6: Total of 106 rds. Bolt handle broke off while closing the bolt on bound 13. Same as C-1

Gun C-4, Completed test with no malfunctions of breakage.

