

Trigger Housing



- Rear spacer of LH side plate removed and replaced with PM rear spacer