

Cust Complaint

I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 002158
 OUTSIDE WORK: SCOPE MOUNTED DATE: 1-23-73
 FROM: SPORTSMAN'S HEADQUARTERS
 FIRED AMMO TYPE: _____ GRAND FORKS, N.D.
 & CONDITION: _____ GUN #: 6451849
 PROOP: R.E.P.-L INSP. 9 TEST: 53 CODE: PU = 6/71
 HEADING: O.K. GR./CAL.: 2006
 BREACH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

HOUSING: .069 AT TOP (MODEL DRAWING: 173) TRIGGER
.173 LOWER END (MODEL DRAWING: 170) METAL CHIPS
AROUND PIN HOLE ON TRIGGER SEAR-TRIGGER
CONNECTOR ENGAGEMENT .010 (MIN. .020)

COMPLAINT: "WILL FIRE WHILE REMOVING UNFIRED SHELL
FROM THE CHAMBER"

INCIDENT: FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3178

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED.
THE BINDING TRIGGER AND SEAR FAILING TO RETRACT
ALONG WITH UNDER MIN. ENGAGEMENT PROBABLY
CAUSED THE FOLLOW DOWN.